

# ELECTRICAL SAFETY RECALL

Sonova Australia Pty Ltd — Phonak & Unitron Plug Adaptor  
Insert provided with Switch Mode Power Supply



**Model affected:** GPE053(A,B) with an output of 5 or 7.5 volts DC supplied from Sonova Australia Pty Ltd for **Phonak or Unitron** products via hearing care professionals and registered hearing equipment distributors in the hearing industry only between **1<sup>st</sup> October 2011 and 31<sup>st</sup> July 2014**.

Equipment using the above switch Mode Power Supplies:

PHONAK	PHONAK	UNITRON
ComPilot	Roger DigiMaster 7000	uDirect
DigiMaster 5000	Roger DigiMaster X	uDirect2
DigiMaster 7000	Roger DynaMic	uTV
DigiMaster X	Roger inspiro audioHub	uTV2
DynaMic	Roger inspiro Premium	iCube
EasyLink	Roger MyLink (02)	
EasyLink+	Roger MyLink (03)	
iCom	Roger Pen	
iCube	Roger WallPilot	
inspiro audioHub	SmartLink+	
inspiro Premium	TVLink Basestation	
MyLink	TVLink S Basestation	
MyLink+	TX-300	
RemoteMic	WallPilot	
Roger Clip-On Mic	ZoomLink+	
Roger DigiMaster 5000		

**Defect:** There is a risk of the adaptor faceplate being dislodged resulting in the internal components being exposed.

**Hazard:** Risk of electrical shock.

**What to do:** If you have been supplied with a power supply with the affected plug adaptor between **1<sup>st</sup> October 2011 and 31<sup>st</sup> July 2014** please contact Sonova Australia Pty Ltd for a replacement unit.

**Contact details:**  
 Website: [www.sonovarecall.com.au](http://www.sonovarecall.com.au)  
 Email: [recall.adaptor@sonova.com](mailto:recall.adaptor@sonova.com)  
 Phone: (02) 8858-1854

See [www.recalls.gov.au](http://www.recalls.gov.au) for Australian product recall information